



Province of the
EASTERN CAPE
EDUCATION

**NATIONAL
SENIOR CERTIFICATE**

GRADE 11

NOVEMBER 2017

**MECHANICAL TECHNOLOGY
MARKING GUIDELINE**

MARKS: 200

This marking guideline consists of 21 pages.

SECTION A: COMPULSORY**QUESTION 1: MULTIPLE-CHOICE QUESTIONS**

1.1	B	✓	(1)
1.2	D	✓	(1)
1.3	A	✓	(1)
1.4	D	✓	(1)
1.5	D	✓	(1)
1.6	A	✓	(1)
1.7	B	✓	(1)
1.8	A	✓	(1)
1.9	C	✓	(1)
1.10	D	✓	(1)
1.11	B	✓	(1)
1.12	B	✓	(1)
1.13	C	✓	(1)
1.14	D	✓	(1)
1.15	A	✓	(1)
1.16	B	✓	(1)
1.17	C	✓	(1)
1.18	B	✓	(1)
1.19	A	✓	(1)
1.20	C	✓	(1)

[20]**QUESTION 2: SAFETY**

- 2.1
- Select the correct type of wheel for the job. ✓
 - Inspect the wheel for cracks. ✓
 - Check if it is not damaged. ✓
 - Make sure the wheel's speed does not exceed the manufacturer's recommendations. ✓
 - Check if the guards are in place. (Any 4 x 1) (4)
- 2.2
- Poor housekeeping ✓
 - Loose clothing ✓
 - Improper use of tools ✓
 - Inaccurate set-up of machines ✓ (4)
- 2.3 It is used to rough - cut large sections of metal ✓ before they are further machined or used in manufacturing. ✓ (2)
- 2.4
- 2.4.1
- Every workplace must be ventilated either by natural or mechanical means so that the air breathed by employees is safe. ✓✓
 - That the concentration therein of any explosive or flammable gas vapour or dust does not exceed safety levels. (Any 2 x 1) (2)
- 2.4.2
- There must be adequate lighting in the work place. ✓✓
 - The lighting on rotating machinery must not cause a flashing effect.
 - Lights and lamps must be kept clean and maintained. (Any 2 x 1) (2)

- 2.5
- Store full cylinders apart from empty ones. ✓
 - Keep cylinders in a cool place and protect them from sunlight and other sources of heat. ✓
 - Always store and use cylinders in an upright position. ✓
 - Store oxygen cylinders away from fuel cylinders. ✓
 - Never stack cylinders on top of each other.
 - Do not bang or work on cylinders. (Any 4 x 1) (4)
- 2.6
- Fixed guards ✓
 - Automatic guards ✓
 - Manual guards
 - Self-adjusting guards (Any 2 x 1) (2)
- 2.7
- Choose the correct sharpened drill for the type of work you need to do and the material you are going to drill. ✓
 - Do not leave the chuck key in the chuck when you are not at the machine. ✓
 - Never leave the machine to run unattended. ✓
 - Clamp the work piece securely to the table and do not hold it by hand. ✓
 - Never try to stop the work piece by hand if it slips from the clamp.
 - A drill should run at the correct speed for the job. (Any 4 x 1) (4)

[24]

QUESTION 3: TOOLS

- 3.1 3.1.1 Inside micrometer ✓ (1)
- 3.1.2 A Contact ✓
B Thimble ✓
C Barrel ✓
E Rod lock ✓
F Contact ✓ (5)
- 3.2
 - It prevents bolts and studs from breaking. ✓
 - It prevents bolts or nuts from loosening. ✓
 - It prevents castings from warping. ✓(3)
- 3.3 Surface grinder ✓ (1)
- 3.4 Sensitive drill press. ✓
Upright drill press. ✓
Radial drill press ✓ (3)
- 3.5 Clean after use. ✓
Never force drill. ✓
Oil machinery regularly. ✓
Check rack on side of pillar column.
Release the table lock before adjusting the table. (Any 3 x 1) (3)
- [16]**

QUESTION 4: MAINTENANCE

- 4.1
 - Viscosity / Viscosity index ✓
 - Flash point / oxidation resistant ✓
 - Burning point / foam resistant ✓
 - Pour point / cold point
 - Adhesion / carbon resistant(Any 3 x 1) (3)

 - 4.2
 - Cost ✓
 - Maintenance ✓
 - Downtime ✓(3)

 - 4.3 To reduce friction ✓✓ (2)

 - 4.4 A loss in efficiency ✓ and eventually mechanical failure ✓ (2)
- [10]**

QUESTION 5: MATERIALS

- 5.1
 - To soften the metal ✓
 - To make steel suitable for bending, drawing or cold work operations ✓(2)

- 5.2 Steel articles to be case hardened need to have outer case converted from low carbon to that of a high carbon steel. ✓✓ (2)

- 5.3
 - A** Charging ladle ✓
 - B** Funnel ✓
 - C** Scrap metal ✓
 - D** Steel ✓
 - E** Slag thimble ✓
 - F** Charging machine ✓
 - G** Charging boxes ✓(6)

- 5.4
 - Time ✓
 - Temperature ✓(2)

- 5.5
 - Heat the temperature between 220 °C and 300 °C and quench. ✓
 - The tempering colours which are oxides of iron, indicate a particular temperature. ✓
 - Each temperature indicate a degree of hardness. ✓
 - The higher the temperature, the softer the resulting metal. ✓
 - Heating can be by means of direct heat from a Buisson or a sand burner.(Any 4 x 1) (4)

- 5.6 The different colour changes ✓ during the heat treatment process. ✓ (2)

- 5.7
- **Hardening:** The process of heat treating steel ✓ to enable it to resist wear or cut other metals. ✓
 - **Tempering:** This is a follow up process from hardening ✓ to relieve the strain induced during the hardening process and to reduce brittleness. ✓ (4)
- 5.8
- 5.8.1 C
- 5.8.2 D
- 5.8.3 A
- 5.8.4 B (4)
- 5.9
- Greater hardness ✓
 - Higher tensile strength ✓
 - More ductility ✓
 - Reduced welding ability (Any 3 x 1) (3)
- [30]**

TOTAL SECTION A: 100

SECTION B: FITTING AND TURNING (SPECIFIC)**QUESTION 6: TERMINOLOGY****6.1 Advantages of taper turning:**

- Set at any required angle. ✓
- Large tapers can be turned. ✓
- External and internal tapers can be turned.

(Any 2 x 1)(2)

Disadvantages of taper turning:

- Can only move short distances. ✓
- Can only be done by hand turning. ✓
- Short distances mean accuracy is not good.

(Any 2 x 1)(2) (4)

- 6.2
- Long tapers ✓
 - Slow tapers under approximately 14° included angle ✓
 - Short slow tapers ✓
 - Short steep tapers ✓
 - Combination of two or a number of the previous categories

(Any 4 x 1) (4)

6.3 6.3.1 Calculate the distance across the flat side:

$$\begin{aligned}\sin \theta &= \frac{x}{90} \\ x &= 90 \sin \theta \checkmark \\ x &= 90 \sin 45^\circ \checkmark \\ &= 90 \times 0,707 \checkmark \\ &= 63,64 \text{ mm} \checkmark \\ \text{Depth of cut} &= \frac{90-x}{2} \\ &= \frac{90-63,4}{2} \checkmark \\ \text{Depth of cut} &= 13,18 \text{ mm} \checkmark\end{aligned}$$

(6)

6.3.2 Calculate the distance across the flat side:

$$\begin{aligned}\sin \theta &= \frac{x}{90} \\ x &= 90 \sin \theta \checkmark \\ &= 90 \sin 60^\circ \checkmark \\ &= 77,94 \text{ mm} \checkmark \\ \text{Depth of cut} &= \frac{90-x}{2} \\ &= \frac{90-77,94}{2} \checkmark \\ &= \frac{12,06}{2} \checkmark \\ &= 6,03 \text{ mm} \checkmark\end{aligned}$$

(6)

- 6.4
- The British system of measurements ✓
 - The metric system of measurement ✓

(2)

- 6.5
- 6.5.1 ASSY – Assembly ✓
- 6.5.2 CHAM – Chamfered ✓
- 6.5.3 DIA – Diameter ✓

(1)

(1)

(1)

[25]

QUESTION 7: TOOLS AND EQUIPMENT

- 7.1 $35 \checkmark + 995 \checkmark = 35,995 \checkmark$ (3)
- 7.2 It provides a quick and accurate means of checking internal measurements. $\checkmark\checkmark$ (2)
- 7.3
- To determine the run-out of a flywheel \checkmark
 - To determine if a crankshaft is bent \checkmark
 - To determine if a lathe is running true \checkmark
 - To determine if two pieces of equipment are the same size (Any 3 x 1) (3)

[8]**QUESTION 8: FORCES**

- 8.1 Moments about **A**: $(B \times 8) = (800 \times 2) + (640 \times 4) + (350 \times 10) \checkmark$
 $= 1600 + 2560 + 3500 \checkmark$
 $B = 957,5 \text{ N} \checkmark$
- Moments about **B**: $(A \times 8) + (350 \times 2) = (640 \times 4) + (800 \times 6) \checkmark$
 $8A + 700 = 2560 + 4800 \checkmark$
 $A = 832,5 \text{ N} \checkmark$ (6)

- 8.2 $\text{Stress} = \frac{\text{Load}}{\text{Area}}$
 $\text{Area} = (32 \times 32) - (28 \times 28) \checkmark$
 $= \frac{20 \times 20^3}{244} \checkmark$
 $= \frac{244}{10^6} \checkmark$
 $= 240 \checkmark$
 $= \frac{20 \times 10^6 \times 10^3}{244} \checkmark$
 $= 81967213,11 \text{ Pa} \checkmark$
 $= 81,97 \text{ MPa} \checkmark$ (6)

- 8.3 Vertical Components:
 $50 \sin 90^\circ - 30 \sin 45^\circ + 45 \sin 0^\circ \checkmark$
 $= 50 - 21,2 + 0$
 $= 28,8 \text{ N} \checkmark$
- Horizontal Components:
 $= 50 \cos 90^\circ + 30 \cos 45^\circ + 45 \cos 0^\circ \checkmark$
 $= 0 + 21,2 + 45$
 $= 66,2 \text{ N} \checkmark$
- $R^2 = X^2 + Y^2$
 $= 66,2^2 + 28,8^2 \checkmark$
 $= 4382,44 + 829,44$
 $= 5211,88 \checkmark$
 $R = 72,2 \text{ N} \checkmark$
- Direction of Resultant:
 $\tan \Theta = \frac{Y}{X}$
 $= \frac{28,8}{66,2} \checkmark$
 $= 0,44$
 $\Theta = 23,5^\circ \checkmark$
- Resultant has a magnitude of 72,2 N in a direction of 23° south of west \checkmark (10)

[22]

QUESTION 9: MAINTENANCE

- 9.1
- When the thin of lubrication is compromised. ✓
 - When a machine is run at a rate higher than at which it was designed to operate. ✓
 - When oil or grease is effectively squeezed out of the machines bearing surfaces. (Any 2 x 1) (2)
- 9.2
- The mass of the rotating element ✓
 - The extent to which the mass is off centre ✓
 - The speed of rotation ✓ (3)
- 9.3
- The friction force is in direct relation to the total force between the two surfaces. ✓
 - It is dependent on the size of the surfaces in contact with each other. ✓
 - It depends on the roughness of the surface and the material the workpiece is made of.
 - It is dependent on the movement speed. (Any 2 x 1) (2)
- 9.4 If a body or system is at rest and stay at rest in any position, it will not turn or rotate under the influence of the force of gravity. ✓ (1)
- [8]**

QUESTION 10: JOINING METHODS

- 10.1
- To hold parts ✓
 - To transmit motion ✓
 - To transmit power
 - To adjust parts with reference to one another (Any 2 x 1) (2)
- 10.2
- 10.2.1 It is the top (outer) surface joining the two sides (flanks) of a screw head. ✓✓ (2)
- 10.2.2 It is the bottom of the groove between the two sides (flanks) of the adjacent threads. ✓✓ (2)
- 10.2.3 It is the centre line running longitudinally through the thread. ✓✓ (2)
- 10.2.4 It is the distance between the crest and the root of the screw thread, measured perpendicular to the axis of the thread. ✓✓ (2)
- 10.2.5 It is the angle included between the sides (flanked) of the thread measured in an axial plane. ✓✓ (2)
- [12]**

QUESTION 11: SYSTEMS AND CONTROL

- 11.1 11.1.1 Anti-clockwise ✓ (1)
- 11.1.2 Gear B turn in a clockwise direction which in turn will allow gear C to turn in an anti-clockwise direction. ✓ (1)
- 11.1.3
- It is an intermediate gear for the rotation of two gears to turn in the same direction. ✓
 - It can assist to reduce the size of the input/output gears whilst maintaining the spacing of the shafts. ✓ (2)
- 11.1.4 It helps to transfer the power ✓ from driven to driver in the same direction. ✓ (2)
- 11.1.5 $\pi \times D_A \times N_A = \pi \times D_B \times N_B$
 $\pi \times 380 \times 900 = \pi \times 150 \times N_B$ ✓
 $N_B = \frac{\pi \times 380 \times 900}{\pi \times 150}$ ✓
 $= 2280 \text{ rpm}$ ✓ (3)
- 11.1.6
- Spur gears are more expensive than belts. ✓
 - Spur gears are noisy at high speeds. ✓
 - Because the spur gears must be in mesh to work their centre, distance are limited. ✓
 - A large amount of stress develops in spur gears. ✓ (4)
- [13]**

QUESTION 12: PUMPS

- 12.1 Gear pump ✓ (1)
- 12.2
- It has the ability to handle a wide range of viscosities. ✓
 - It is less sensitive to cavitation. ✓
 - Dit is relatief maklik om te onderhou en te herbou. ✓
 - High speed
 - High pressure
 - No overhung bearing loads
 - Relatively quiet operation (Any 3 x 1) (3)
- 12.3
- A** Outlet port ✓
 - B** Rotor ✓
 - C** Vane ✓
 - D** Pump housing ✓
 - E** Inlet port ✓ (5)
- 12.4
- Complex housing ✓
 - Not suitable for high pressures ✓
 - Not suitable for high viscosity ✓
 - Not good with abrasives (Any 3 x 1) (3)
- [12]**

TOTAL SECTION B: 100

SECTION C: AUTOMOTIVE (SPECIFIC)**QUESTION 13: TOOLS AND EQUIPMENT**

- 13.1
- To determine the run-out of a flywheel ✓
 - To determine if a crankshaft is bent ✓
 - To determine if a work piece in the lathe is running true ✓
 - To determine if two pieces of equipment are the same size (Any 3 x 1) (3)
- 13.2
- Do not over tighten the locking screw. ✓
 - Do not force the telescopic plunges into the bore. ✓
 - Store gauges safely away after use. ✓
 - Take care when removing the telescopic gauge after measurement was taken. (Any 3 x 1) (3)
- 13.3 newton meter (Nm) ✓ (1)
- 13.4
- It prevents bolts or studs from breaking. ✓
 - It prevents bolts and studs from loosening. ✓
 - It prevents castings from warping. (Any 2 x 1) (2)

[9]**QUESTION 14: ENGINES**

- 14.1
- Mechanical fuel pumps ✓
 - Distributer ✓
 - Oil pumps (Any 2 x 1) (2)
- 14.2 They transmit rotary movement of the crankshaft gear to the camshaft gear so that the camshaft rotate at half speed of the crankshaft. ✓✓ (2)
- 14.3 Tensioner ✓ (1)
- 14.4 Eight (8) ✓ (1)
- 14.5
- 14.5.1
- It controls the incoming and outgoing gases in the engine. ✓
 - Opens and closes the port. (Any 1 x 1) (1)
- 14.5.2 To keep them properly closed to prevent the loss of power ✓ (1)
- 14.6
- 14.6.1
- When the injector is energised, an electromagnet moves the plunger. ✓
 - This opens the valve, allowing pressurised fuel to squirt out through a tiny hole. ✓
 - When not energised, a spring pushes the plunger back down, allowing no fuel to exit. ✓
 - How much the plunger opens is regulated by the amount of electricity sent to the fuel injector, ✓ causing the magnetic field to be stronger. ✓ (5)
- 14.6.2
- Reliable ✓
 - Cost effective ✓
 - Physically smaller (Any 2 x 1) (2)

[15]

QUESTION 15: SYSTEMS AND CONTROL

- 15.1 • Spiral bevel ✓
 • Hypoid ✓ (2)
- 15.2 Transmit torque ✓ (1)
- 15.3 15.3.1 • To transmit force from the steering centre link or the rack gear to the steering knuckle. ✓
 • This causes the wheel to turn. ✓
 • The outer tie rod end connects with an adjusting sleeve, which allows the length of the tie rod to be adjustable. ✓
 • This adjustment is used to set a vehicle's alignment. (3)
- 15.3.2 • It is used for allowing free movement on two planes at the same time, including rotating in those planes. ✓
 • Combining two such joints with control arms enables motion in all three planes, ✓ allowing the front end of an automobile to be steered and a spring and shock (damper) suspension to make the ride comfortable. ✓ (3)
- 15.3.3 • It changes the rotary motion of a crank or the steering box to a second crank or link in a different plane or axis. ✓
 • It converts the sweeping motion of the steering box to the linear motion ✓ needed to pull the tie rods and ultimately turn the vehicle's wheels. ✓ (3)
- 15.4 • Reduced comfort while driving or travelling. ✓
 • Loss of stability and driver control. ✓
 • Life of tyre, transmission parts, springs, wheel bearings and steering linkages are shortened by the excessive bouncing motion of the wheels and body. ✓ (3)
- 15.5 It is fitted to reduce body roll above the spring and axles ✓ when the vehicle is cornering and thus helps the car on a more even keel. ✓ (2)
- 15.6 • Smoother engine performance because the torsion of the crankshaft is not concentrated on a specific section, but is distributed evenly over the length of the crankshaft ✓
 • The heat caused by the power strokes is evenly distributed and prevents local overheating or cooling: ✓
 ○ causing minimal vibration to improve engine balance ✓
 ○ achieving smooth running
 ○ achieving longer engine life
 ○ causing user comfort ✓ (4)
- 15.7 1-4-2-6-3-5 ✓ (1)

- 15.8 15.8.1
- A much higher voltage from the ignition coil is required ✓ to bridge the gap and may cause the ignition coil to overheat. ✓
 - Misfiring occurs at high engine revolutions and at engine load because of insufficient voltage to bridge the gap. ✓
 - The engine will be difficult to start, especially during cold conditions. ✓
- (4)
- 15.8.2
- The spark duration will be very quick and the spark will be thin and weak. ✓
 - The effects of this may be bad starting and high exhaust emission levels. ✓
 - Will result in an increase in fuel consumption. ✓
 - A worn engine will cause carbon deposits to bridge the gap and will result in misfiring. ✓
 - Uneven engine performance will cause loss of power. ✓
- (4)
[30]

QUESTION 16: MAINTENANCE

- 16.1
- Lack of lubrication ✓
 - Overloading ✓
 - Friction ✓
- (3)
- 16.2
- Type of material ✓
 - Diameter of the drill bit ✓
 - Material of which the drill is made ✓
 - Firmness with which the drill is made
 - Condition of the machine
 - Use of cutting fluid
 - Rate of feed
- (Any 3 x 1) (3)
- 16.3
- The pump is very efficient and can develop high pressure ✓
 - There are no reciprocating parts which can cause vibrations ✓
 - The drive is always positive ✓
 - It has no valve or springs
- (Any 3 x 1) (3)
- 16.4
- Can-type ✓
 - Cloth-type ✓
 - Filter-paper type
 - Screw-on filters
- (Any 2 x 1) (2)
[11]

QUESTION 17: FORCES

17.1 IP = Plan where $P = 1\,500\text{ kPa} = 1\,500 \times 10^3$

$$L = 95\text{ mm} = 95 \times 10^{-3}$$

$$A = \frac{\pi D^2}{4}$$

$$N = 3000\text{ r/min} = \frac{3000}{60 \times 2} = 25\text{ r/s}$$

$$n = 4\text{ (No. of cylinders)}$$

$$\begin{aligned} IP &= \frac{1500 \times 10^3 \times 95 \times 10^{-3} \times \pi (0,07)^2 \times 25 \times 4}{4} \checkmark\checkmark\checkmark \\ &= 69\,825\text{ watt } \checkmark \\ &= 69,825\text{ kW } \checkmark \end{aligned}$$

(5)

17.2 Torque = Force \times radius \checkmark

$$= 250 \times \frac{400}{1000} \checkmark$$

$$= 100\text{ Nm } \checkmark$$

(3)

17.3 It is the ratio of compression of the inlet charge \checkmark during the compression stroke in the combustion chamber \checkmark to the total volume of the cylinder. \checkmark

(3)

17.4 SV = Area of cylinder \times Length of stroke

$$= \frac{\pi D^2}{4} \times 120 \checkmark$$

$$= \frac{3,142(0,11)^2}{4} \times 0,12 \checkmark$$

$$= 0,00114\text{ cm}^3 \checkmark \text{ or } 1,14 \times 10^{-3}\text{ m}^3$$

$$\begin{aligned} \text{Compression ratio} &= \frac{\text{Swept Volume} + \text{Clearance Volume}}{\text{Clearance Volume}} \checkmark \\ &= \frac{0,00114 + 95}{95} \checkmark \\ &= 2,2 \checkmark \end{aligned}$$

(6)

17.5 17.5.1 joule (J) \checkmark

(1)

17.5.2 watt (W) \checkmark

(1)


17.6 • Indicated mean effective pressure (IMEP) \checkmark

• Break mean effective pressure (BMEP) \checkmark

(2)

17.7 17.7.1

Pulling \checkmark



Force $\checkmark\checkmark$

(3)

17.7.2

Pushing \checkmark




$\checkmark\checkmark$

(3)

17.7.3

Cutting \checkmark



$\checkmark\checkmark$

(3)

[30]

QUESTION 18: TERMINOLOGY

- 18.1 18.1.1 The entrepreneur interested in opening a workshop ✓ should be sure that he/she has the ability to manage the business as well as to keep the customer and staff happy. ✓ (2)
- 18.1.2 The capital needed to buy or lease the premises, ✓ the availability of a bank loan and the interest rate payable should be established. ✓ (2)
- 18.1.3 The number of workers at the work place other than the general manager e.g. workshop foreman, ✓ office staff, receptionist, mechanics, apprentices and labourers. ✓ (2)
- 18.1.4 The site where you going to do business to attract customers, e.g. close to a main road, ✓ or in a highly-developed area or even in a densely populated residential area. ✓ (2)


[8]**TOTAL SECTION C: 100**

SECTION D: WELDING AND METALWORK (SPECIFIC)

QUESTION 19: JOINING METHODS


- 19.1 19.1.1 Single bevel-butt ✓✓ (2)
- 19.1.2 Fillet joint ✓✓ (2)
- 19.1.3 Double bevel butt ✓✓ (2)

19.2 Flat position ✓



✓✓ (3)

Horizontal position ✓



✓✓ (3)

- 19.3 A Parent or base metal ✓
- B Face of weld ✓
- C Fusion zone ✓
- D Toe of weld ✓
- E Heat affected zone ✓
- F Root face ✓

(6)
[18]

QUESTION 20: TOOLS AND EQUIPMENT

- 20.1
 - Taper taps ✓
 - Intermediate ✓
 - Plug/bottoming tap ✓(3)

20.2 20.2.1 6,8 mm ✓ (1)

20.2.2 8,5 mm ✓ (1)

20.2.3 10,2 mm ✓ (1)

20.3 It is a shearing machine. ✓ (1)
[7]

QUESTION 21: FORCES

21.1 VC : $8 \sin 60^\circ = 6,9 \text{ N}$ ✓
 $6 \sin 0^\circ = \underline{0 \text{ N}}$ ✓
 $6,9 \text{ N}$ ✓
 $R^2 = X^2 + Y^2$
 $= 10^2 + 6,9^2$
 $= 100 + 47,61$
 $R = \sqrt{147,61}$
 $R = 12,15 \text{ N}$ ✓


HC : $8 \cos 60^\circ = 4 \text{ N}$ ✓
 $6 \cos 0^\circ = \underline{6 \text{ N}}$ ✓
 10 N ✓

Calculate the direction of the resultant as follows:

$\tan \emptyset = \frac{\text{Sum } Y}{\text{Sum } X}$
 $= \frac{6,9}{10}$
 $= 0,69$
 $\emptyset = 34,6^\circ$ ✓

The resultant has a magnitude of 12,15 N ✓ in a direction of 34,6° NE (North East) ✓ (10)

21.2 Scale 1 N = 20 mm



(7)
[17]

QUESTION 22: MAINTENANCE

- 22.1
- Check electrical switches and the conditions of wiring. ✓
 - Lock out and tag the machine and check the guarding as follows: ✓
 - Check that all guards are secure and function correctly.
 - Clean machine of all foreign matter.
 - Check whether the upper roller can freely be adjusted between upper and lower limits.
 - Check the machines general operations.
 - Check if the bottom two rollers can rotate freely in both the positive and reverse directions. (Any 2 x 1) (2)
- 22.2 It will result in wear and damage ✓ to moving components. ✓ (2)
- 22.3 To cut or punch steel ✓ that is thicker than the rated thickness ✓ (2)
- [6]**



QUESTION 23: JOINING METHODS

- 23.1 To prevent distortion ✓ as the heat of the fusion weld moves progressively along the weld joint. ✓ (2)
- 23.2
- Butt-joint ✓
 - Lap-joint ✓
 - Corner-joint ✓
 - Corner T-joint ✓
 - Edge-joint ✓ (5)
- 23.3
- 23.3.1 Flat-position ✓ (1)
- 23.3.2 Horizontal position ✓ (1)
- 23.3.3 Vertical position ✓ (1)
- 23.3.4 Overhead position ✓ (1)
- 23.4
- Forehand ✓
 - Perpendicular ✓
 - Backhand ✓ (3)
- 23.5
- Incomplete penetration ✓
 - Porosity
 - Undercutting
 - Weld craters and faulty starts
 - Slag inclusion
 - Cracks (Any 1 x 1) (1)

[15]

QUESTION 24: TERMINOLOGY


24.1



[19]


QUESTION 25: STEEL SECTIONS

25.1 25.1.1




(
2
)

25.1.2




(
2
)

25.1.3




(
2
)

25.1.4



(
2
)

25.1.5




(
2
)

25.2 It is the process of cutting out a section of steel ✓ in order to form a snug fit with the flange of a corresponding section. ✓ (2)

- 25.3
- Column cap ✓
 - Knee brace ✓
 - Welded gantry bracket ✓
 - Beam to beam connection
 - Beam to station connection
 - Bending moment connection
 - Extension of steel stanchions
 - Bolted base
 - Welded column
 - Plate anchor
 - Welded stay
- (Any 3 x 1) (3)

25.4 Steel mills ✓ (1)



TOTAL SECTION D: 100
GRAND TOTAL: 200